

## Product Advisory

Issue Date: 30-June-2022

**Change Description:**

BCM65060A1 will be replaced by BCM65060B1

**Parts Affected:**

BCM65060A1IMLGT  
BCM65060A1IMLG

**Description and Extent of Change:**

This product advisory is to give an early notification that Broadcom has had to move its G.fast line driver to a new fab to ensure continued delivery. This will result in a B1 revision to the A1 devices listed above.

**Reasons for Change:**

The fab that the A1 revision was produced in has been shut down.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification has been performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

**Effective Date of Change:**

Product shipments using this change will begin after 12/30/22. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.

**Qualification Data:**

Qualification Data should be available by 9/1/22. Samples are available now and can be requested for customer qualification.

**Software / Firmware Update:**

Firmware changes are required as part of this product change, please check with your Broadcom FAE to get access to the firmware update.

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.