BROADCOM

Product Obsolescence Notification

Issue Date: September 23, 2021

Dear Customer:

Broadcom regrets to announce the immediate obsolescence of the following products, as Broadcom's wafer supplier is discontinuing the manufacture of wafers for these products. Broadcom will not be able to accept any new orders under the obsoleted part numbers.

Broadcom Part Numbers	Description	Suggested Replacement
BCM4708C0KFEBG	1.0GHz dual core A9 w/ switch PHY	BCM58713DB0KFEB20G
BCM4708CS0002	Router: CPU+WiFi Radios	BCM58713DB0KFEB20G
BCM4709C0KFEBG	1.4GHz dual core A9 w/ switch PHY	BCM58713DB0KFEB20G
BCM58523BB1KF12G	Dual core A9 SoC with 2 GPHYs	BCM58713DB0KFEB20G
BCM58525BB1KF14G	Dual core 1.2GHz A9 w/ 2GPHY	BCM58713DB0KFEB20G
BCM58535BA1KF12G	1.2GHz 2-cre Cortex-A9 with 2.5G SGMI	BCM58713DB0KFEB20G
BCM58625BB1KF12G	Dual core 1.2GHz A9 w/ 5 GPHY	BCM58713DB0KFEB20G
BCM58625SA00	58625 1.2GHz chipset	N/A

Please contact your Broadcom Sales Representative for questions or concerns.

_____

Please contact your Broadcom Field Sales Engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.