


# Product Change Notification

## ROTARY POSITION SENSORS



March, 2017

### **Bourns® Model 3382** **12 mm Rotary Position Sensor** ***Material Change***

Bourns is making changes to the plastic, which is used to mold the substrate and cover for the [Model 3382](#) 12 mm Rotary Position Sensor. The plastic is changing from Genestar GN2330 to Unitika Xecot AV110A35-KX1. The product's Material Declaration Sheet provides more information. The reason for this change is cost and availability.

There is no change to the form, fit, function, quality or reliability of the sensor.

A list of affected part numbers is on the following page.

Implementation dates are as follows:

*Last time buy date for products with the existing plastic: May 15, 2017*

*Bourns will begin phasing in this new plastic: June 1, 2017*

*Date that manufacturing of existing product will cease: June 1, 2017*

*First date code using the above changes: 722T*

Product samples are available upon request.

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

### Affected Part Numbers

3382G-1-103G	3382G-GK6-103G	3382H-1-103
3382G-1-104G	3382G-PM6-103G	3382H-1-104
3382G-1-252G	3382G-RP1-103G	3382H-1-252
3382G-1-2534G	3382G-RP2-472G	3382H-1-253
3382G-1-253G	3382G-RP3-472G	3382H-1-502
3382G-1-502G	3382G-RP4-472G	3382H-1-503
3382G-1-503G	3382G-RP6-472G	3382H-2-103
3382G-2-103G	3382G-RP7-472G	3382H-2-253
3382G-2-104G	3382G-RP8-103G	3382H-2-502
3382G-2-253G	3382G-RR1-103G	
3382G-2-502G	3382G-RR1-502G	
3382G-2-503G	3382G-RR2-103G	