



Product/Process Change Notice - PCN 15_0242 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

PCN Title: ADuCM350 Metal Edit Change

Publication Date: 02-Dec-2015

Effectivity Date: 01-Mar-2016 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

Minor Metal Edit is required in HFR COSC block to improve system robustness in clocking system.

Reason For Change

Changes are to improve system robustness in clocking system.

Impact of the change (positive or negative) on fit, form, function & reliability

There is no negative impact on fit, form, function or reliability of the device

Product Identification *(this section will describe how to identify the changed material)*

Date code will be advised on later revision of PCN when available.
The CHIPID register will be changing from 0x0212 to 0x0214

Summary of Supporting Information

The change made has been verified in both characterization analysis and bench testing.

Supporting Documents None

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN_Americas@analog.com

Europe: PCN_Europe@analog.com

Japan: PCN_Japan@analog.com

Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Added Parts On This Revision - Product Family / Model Number (2)

ADUCM350 / ADUCM350BBCZ

ADUCM350 / ADUCM350BBCZ-RL

Appendix B - Revision History

Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	02-Dec-2015	01-Mar-2016	Initial Release

Analog Devices, Inc.

DocId:3483 Parent DocId:None Layout Rev:7