

**Customer Information Notification**

202012003I

**Issue Date:** 20-Dec-2020  
**Effective Date:** 21-Jan-2021

Here's your personalized quality information concerning products Digi-Key purchased from Nexperia. For detailed information we invite you to view this notification online



**Change Category**

- |  |   |  |   |   |
|--|---|--|---|---|
| <input type="checkbox"/> Wafer Fab Process   | <input type="checkbox"/> Assembly Process   | <input type="checkbox"/> Product Marking           | <input type="checkbox"/> Test Location  | <input type="checkbox"/> Design                         |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification  | <input type="checkbox"/> Test Process   | <input checked="" type="checkbox"/> Errata              |
| <input type="checkbox"/> Wafer Fab Location  | <input type="checkbox"/> Assembly Location  | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Electrical spec./Test coverage |

**Correction of Fall Time in BUK6Y33-60P Datasheet**

**Information Notification**

This notification is to inform our customers about a correction of the fall time (tf) information in the datasheet of the type BUK6Y33-60P.

Adobe will no longer be supporting Flash Player after 31 December 2020 and Adobe will block Flash content from running in Flash Player beginning 12 January 2021. Therefore it is not possible to access the Nexperia ePCN-tool anymore. Please use the below links to access related documentation to this change notification.

Existing data sheet:

[https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P\\_Datasheet\\_Existing.pdf](https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P_Datasheet_Existing.pdf)

New data sheet:

[https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P\\_Datasheet\\_New.pdf](https://qcm.nexperia.com/change-notification-epcn/BUK6Y33-60P_Datasheet_New.pdf)

**Why do we issue this Information Notification**

To have the correct value in the datasheet. An error (missing number) for the fall time (tf) of the BUK6Y33-60P was detected which has been corrected.

**Identification of Affected Products**

Product identification does not change

## Impact

no impact to the product's functionality anticipated.

### Data Sheet Revision

A new datasheet will be issued

### Disposition of Old Products

Not applicable

## Remarks

Existing and New datasheet included in CIN attached files

## Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact Nexperia "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local Nexperia Sales Support team.

At Nexperia B.V. we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

## About Nexperia B.V.

We at Nexperia are the efficiency semiconductor company. We deliver over 90 billion products a year and as such service thousands of global customers, both directly and through our extensive network of channel partners. We are at the heart of billions of electronic devices in the Automotive, Mobile, Industrial, Consumer, Computing, and Communication Infrastructure segments.

You have received this email because you are a designated contact or subscribed to Nexperia Quality Notifications. Nexperia shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.



[Nexperia](#) |

Nexperia B.V.  
Jonkerbosplein 52 6534 AB Nijmegen, The Netherlands

© 2017 Nexperia. All rights reserved.

### **Affected Part Number**

BUK6Y33-60PX