



## Product Change Notification (PCN)

PCN Number	503200	Date Issued	June 01, 2018
Reason for Change	Supplier Change		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	February 28, 2018		
Sample Availability Date (Changed Part)	February 28, 2018		
Planned Implementation Date	November 30, 2018		
Method of Identifying Change	Date code		

Before Change

After Change

- Series 502382, 502386, 504189, 504194, 504195, 505433, 505448, 505567 and 505568 metal strips is changing its metal strips supplier.
- Due to increase of the demand, current supplier having capacity constraints to cater Molex demand.

- Metal Strip raw material will be provided by new supplier.
- Product Impact:
  - They will be no impact on the product including fit, form or function.
  - There is no change in process or design.
- Qualification Reports and samples available upon request.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:503200**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)

Molex Part #

5023820270  
5023820272  
5023820370  
5023820372  
5023820470  
5023820472  
5023820570  
5023820572  
5023820670  
5023820672  
5023820770  
5023820772  
5023820870  
5023820970  
5023821070  
5023821072  
5023821170  
5023821272  
5023821472  
5023821572  
5023860270  
5023860370  
5023860470  
5023860572  
5023860670  
5023860672  
5023860770  
5023860772  
5023860870  
5023861070  
5023861170  
5023861270  
5023861470  
5023861570  
5041940370  
5041940470  
5041940570  
5041950270  
5041950470  
5041950570

**Part numbers affected:**

502382-0270	502382-0370	502382-0470	502382-0607
502381-1272	504194-0270	504194-0370	504195-0470