



Product Discontinuance Notice - PDN 16_0036 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Select iSensor Product Obsolescence (ADIS16266, ADIS16367, ADIS16229 & ADIS16000)

Publication Date: 20-Apr-2016

Last Time Buy Date: 30-Sep-2016

Last Time Ship Date: 31-Mar-2017

Revision Description:

Initial Release

Reason For Discontinuance

Low historical demand

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com

Europe: PDN_Europe@analog.com

Japan: PDN_Japan@analog.com

Rest of Asia: PDN_ROA@analog.com

PDN 16_0036 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADIS16000AMLZ	ADIS16000	NONE	N/A	
ADIS16229AMLZ	ADIS16229	NONE	N/A	
ADIS16266/PCBZ	ADIS16266	ADIS16265/PCBZ	Yes	
ADIS16266BCCZ	ADIS16266	ADIS16265BCCZ	Yes	
ADIS16367BMLZ	ADIS16367	ADIS16448BMLZ	No	
ADIS16COM1/PCBZ	ADIS16COM	NONE	N/A	

Appendix A - PDN 16_0036 Revision History

Rev	Publish Date	Rev Description
Rev. -	20-Apr-2016	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1047 Layout Rev:2 Parent DocId:None