

PCN Number:	20130719001			PCN Date:	07/24/2013
Title:	TL4242-Q1 datasheet - CMS C1306189				
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037	Dept:	Quality Services
Change Type:					
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process	<input type="checkbox"/>	Assembly Materials
<input type="checkbox"/>	Design	<input checked="" type="checkbox"/>	Electrical Specification	<input type="checkbox"/>	Mechanical Specification
<input type="checkbox"/>	Test Site	<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Wafer Bump Material	<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Wafer Fab Materials	<input type="checkbox"/>	Wafer Fab Process

PCN Details

Description of Change:

Texas Instruments publication SLVS732 has changed as described below. Figure 6 has been added to page 7.

TYPICAL CHARACTERISTICS (continued)

ST PIN VOLTAGE
versus
ST PIN PULLDOWN CURRENT




Figure 6.

Reason for Change:
Customer request
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):
No anticipated impact. This is a specification change announcement only. There are no changes to the actual devices.
Changes to product identification resulting from this PCN:
None
Product Affected:
TL4242QKTTRQ1 TL4242TDRJRQ1

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com