

Product Discontinuation



PD_177_20

■ Last Order Date:	2020-12-31
■ Last Delivery Date:	2021-06-30

Reason: Phase out of Infineon front end site Temecula according to Infineon strategy.

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
BSO203P H	SP000613858	BSO203PHXUMA1	PG-DSO-8	none			
BSS340NW H6327	SP001385374	BSS340NWH6327XTSA1	PG-SOT323-3	none			
IRF7410TRPBF-1	SP001577368	IRF7410TRPBF-1	SO8	none			
IRF7416TRPBF-1	SP001555334	IRF7416TRPBF-1	SO8	none			
IRF840PBF	SP001565770	IRF840PBF	TO220	none			
IRFC7314B	SP001560292	IRFC7314B	N.A.	none			
IRLML2803TRPBF-1	SP001558326	IRLML2803TRPBF-1	SOT23	none			

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.