



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000996

DATE: 09-Jun-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX1996AETI+	N/A	09-Jun-2020	06-Dec-2020	Part can no longer be manufactured
Discontinuance	MAX20003DATPA/VY+	MAX20003EATPA/VY+	09-Jun-2020	06-Dec-2020	Part can no longer be manufactured
Discontinuance	MAX20335AEWX+	N/A	09-Jun-2021	06-Dec-2021	Part can no longer be manufactured
Discontinuance	MAX20335AEWX+T	N/A	09-Jun-2021	06-Dec-2021	Part can no longer be manufactured
Discontinuance	ZA9L1033NW2CSGA429	N/A	09-Jun-2021	06-Dec-2021	Part can no longer be manufactured
Discontinuance	ZA9L106DNW2CSGA434	N/A	09-Jun-2021	06-Dec-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 10-Jul-2020