



Product Change Notification (PCN)

PCN Number Date Issued

Reason for Change

Change Type Description

Assessment of Change

Internal Molex Qualification Date

Sample Availability Date (Changed Part)


Planned Implementation Date

Method of Identifying Change

RELEASED

Before Change

After Change



Overview

- Change description:
 1. Avoid the risk that post of connector has interference with hole of PCB, all of RA and Vertical(42ckts/80ckts) post diameter change to $\phi 0.82+0.03/-0.15$, it doesn't impact the customer application
 2. Change the plating from tin to gold flash on solder side of the SMT (ONLY SINGLE SIDE FLASHED) to avoid oxidized
 3. Change the plating location from Molex to Molex vendor and plating tin change to selective plating from overall plated on solder nail of leg shell in XD shell product series (part number 1719833042/1731620338)
- Product Impact
 - Product quality will be improved after the change, there is form, fit impact to the part.
- Part Number Impact
 - see attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator_cms@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505558**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

1719820142

1719821142

1719832042

1719833042