





**Method to Identify Change:**

code, top marking

**Qualification Report:**

Not applicable

**Revision History:**

**July 22, 2019:** Issued final notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

**Attachment(s):**

[PCN\\_KSRA-18DKCY941\\_Pre\\_and\\_Post\\_Change.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

BM20SPKS1NBC-0001AA

BM20SPKS1NBC-C001AA

BM20SPKS1NBC-C002AA

BM20SPKS1NBC-T001AA

BM20SPKS1NBC-Y003AA

BM20SPKS1NBC-Y202AB

BM20SPKS1NBC-Y202DP

BM20SPKS1NBC-Y202MA